







national gridESO









Western Link status: Available

Commentary

The market was mostly long for the duration of the morning, from late morning onwards becoming mostly short. There was a shortfall in Wind during the day.

Overnight to the early hours BM actions were taken due to Voltage constraints around the South and East Coast. System Inertia was managed throughout the day via Trades, predominantly on the interconnectors. Additional BM actions were required to manage Voltage and System Inertia from the morning throughout the day.